

Air Toxics in South Carolina "Impacts to Area Sources"

R. Shawn Gerald Air Toxics Section

Maximum Achievable Control Technology (MACT) Standards

- Section 112(d) of the CAAA of 1990
- National Emissions Standards for Hazardous Air Pollutants (NESHAP)
- Affects all major sources of HAP (≥ 10/25 tons/year), AND some minor (area) sources of HAP
- Currently 90 source category-specific standards
- Technology Based Standards

Area Source/Urban Air Toxics Program

- Section 112(k) of the CAAA of 1990
 - Affects area sources (< 10/25 tpy HAP)
 - Achieve substantial reduction in emissions of HAP from area sources and equivalent reduction in public health risk
 - -≥ 75% reduction in incidence of cancer attributable to HAP emissions from area sources

Area Source Standards

- Generally Available Control Technology (GACT) Standards - less stringent than MACT
- Performance based strategy?
- 70 listed categories
- 16 standards completed to date
- 55 standards due by June 2009 (courtordered deadline) - source categoryspecific

Area Source Standards Schedule

Category	Due Date
Other Solid Waste Incinerators (OSWI)	11/2005 (completed)
Oil and National Gas Production	06/2005 (proposal) 12/2006 (promulgate)
Hospital Sterilizers	10/2006 (proposal) 12/2007 (promulgate)
Gasoline Distribution Stage 1	10/2006 (proposal) 12/2007 (promulgate)
Stationary Internal Combustion Engines	10/2006 (proposal) 12/2007 (promulgate)

Area Source Standards Schedule

Category	Due Date
Primary Copper Smelting	10/2006 (proposal) 12/2006 (promulgate)
Secondary Copper Smelting	10/2006 (proposal) 12/2006 (promulgate)
Primary Nonferrous Materials	10/2006 (proposal) 12/2006 (promulgate)
Polyvinyl Chloride & Copolymer Production	10/2006 (proposal) 12/2006 (promulgate)

Area Source Standards Schedule

6 Source Categories	06/15/2007
10 Source Categories	12/15/2007
10 Source Categories	06/15/2008
10 Source Categories	12/15/2008
10 Source Categories	06/15/2009

Area Sources' Role

- Comment on proposed regulations
 - Control requirements
 - Work practices
 - Permit requirements
 - Recordkeeping/reporting
- Look for outreach packages
- Call US!!!!!!!
- Be prepared: time factor
 - compliance dates will vary

DHEC's Role

- Air Toxics Section, Bureau of Air Quality
- Implements Federal and State Air Toxics Programs (MACT, EPCRA, 112(r), Area Source, etc...)
- Review reports
- Technical assistance to industry
- Applicability determinations
- Outreach
- Assist in inspections

Who to Call

- General Air Toxics Questions
 - Liz Basil, Manager 803.898.4126

- Area Source Questions
 - Mary Peyton Wall 803.898.4064